Ohio EPA - Daily Discharge Monitoring Report - Form 4500

SUBMISSION ID:

FACILITY:

LOCATION:

COUNTY:

DISTRICT:

4996

American Energy Corp Century Mine

43521 Mayhugh Hill Rd Twp Hwy 88 Beallsville, OH 43716

Belmont SEDO

STATUS:

ANALYST:

Original 0IL00091*GD

PERMIT NUMBER: STATION CODE: MONITORING PERIOD:

REPORTING LAB:

601 2008-02-01 To: 2008-02-29 Tra-Det Inc.

Laura K Wright

NO DISCHARGE INDICATOR: AL

PARAMETER	Nitrogen, Ammonia (NH3)	CBOD 5 day						
PARAMETER CODE	00610	80082						
UNITS	4106	4106						
FREQUENCY SAMPLING TYPE	1 / 2 Weeks Grab	1 / 2 Weeks Grab						
2008-02-01	Giab	Glab						
2008-02-02								<u></u>
2008-02-03								
2008-02-04	:							
2008-02-05								
2008-02-06								
2008-02-07								<u> </u>
2008-02-08								
2008-02-09			<u> </u>					
2008-02-10								
2008-02-11								*****
2008-02-12								
2008-02-13								
2008-02-14								
2008-02-15								
2008-02-16								
2008-02-17								,
2008-02-18								
2008-02-19								
2008-02-20								
2008-02-21								
2008-02-22			1					
2008-02-23			<u> </u>			-		
2008-02-24			 					
2008-02-25						the state of south	4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	
2008-02-26								
2008-02-27	!							
2008-02-28								
2008-02-29								
Minimum								
Maximum								
Average					Ī., .			
Count Name of Passansible Officia	1 [<u>.</u>	<u> </u>	e:	anotum of Bassassials	Official or Authorized	C. L
Name of Responsible Officia or Authorized Representative	with the information:	submitted herein and ba	ised on my inquiry of the	ose	51;	gnature of Responsible Represe		Submission Date/Time
Adam Hartley	individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.							2008-03-19
Page 19								

https://ebiz.epa.ohio.gov/edwr.web/page/report/viewWithXslt.do?actType=viewWithXslt...

2/22/2011